

RESTRAINT PLUS+®

Replacement High Pressure Flow Line Restraints

Applications

- Frac Iron Securement
- Injection Wells
- Surface Flow Lines
- Surface Valves
- Surface Manifolds

Warnings

- Not for Lifting
- Shall not be used in temperatures in excess of 194°F, or below minus -40°F
- Waterproof restraints available for freezing climates

Hitch Methods

- Half Hitch
- Spine & Rib

Made in USA



Size & PSI Charts

Model	Iron Size	Max Pressure
Restraint Plus+® Red	2"	15,000 psi
	3"	8,000 psi
	4"	5,000 psi
Restraint Plus+® Blue	2"	20,000 psi
	3"	15,000 psi
	4"	10,000 psi
Restraint Plus+® Orange	2"	20,000 psi
	3"	15,000 psi
	4"	15,000 psi

Kilgore, TX
903-984-9691

Midland, TX
800-262-2099

Shreveport, LA
318-221-0894

Stocking Distributor:

Pleasanton, TX
830-569-2700

Alice, TX
361-664-7424

www.Matex.us

